

Module : TCXO 14.400 MHz

Accuracy : Calibrated Error < ± 0.1 ppm (Less than 1 Hz error at 14.4 MHz)

Supply voltage : 4.75 to 5.25V

